

MINUTES Trustee Meeting December 16, 2020, 10:00 a.m. Conference call

On conference: Trustee Chair Dale Gregory, Trustee Bryan Miles, Trustee John Revitt, Administrator Janine Reimer. Operator Courtney Robertson was not present, as she was tending to SSID operations in the morning.

1.	Approval of the agenda	. Moved B.Miles, 2nd J.Revitt. Carried.
----	------------------------	---

2. Approval of the minutes

- 2a. September 23 Trustee Meeting....... Moved J.Revitt, 2nd B.Miles. Carried.2a (i) Business arising from the Minutes none
- 2b. September 23 In Camera Meeting...... Moved J.Revitt, 2nd B.Miles. Carried. 2b (i) Business arising from the Minutes to be discussed in camera

3. Motion to move in camera...... Moved J.Revitt, 2nd B.Miles. Carried. The trustees came out of in camera, and reported having discussed 2 issues.

4. Operator's report......J.Reimer, for Operator C.Robertson

4a. New Generator-1 and transfer switch

The new transfer switch had twice failed, each time resulting in both generators cycling on and off every 15 minutes, in unison, i.e. not alternating. The operator and Newport Electric arrived on site to correct the problem November 28, and determined that the issue was the transfer switch's motherboard. A new motherboard was installed on December 9, but also failed. Electrician Charlie Bird contacted Thompson, the supplier of the transfer switch, to reiterate the importance of this installation for the water district. Thompson came to SSID, no charge, on December 16 to ensure the installation worked this time.......Operator to report update.

4b. Hydrant report

The operator's written hydrant report had indicated that hydrant-11 was a candidate for replacement due to a compromised base. The report also showed 5 hydrants with poor or slow drainage which would require excavation and repacking with drainage rock. The operator had noted to the administrator that these problem hydrants might best be replaced rather than serviced, as they are nearing their scheduled replacement date.

The administrator scheduled replacements of hydrant-11 and poor-drainage hydrant-9 in 2021, then 2 other poor-drainage hydrants in 2022, and 2 slow-drainage hydrants in 2023. The balance of 7 no-problem hydrants could wait for replacement over the 3 years 2027-2029. Trustee Miles asked that this schedule be added to the Calendar of Events.

The operator would be providing an estimate on 2 new hydrants and services and hard costs to install them in 2021.

2785 Vancouver Blvd, Savary Island, BC VoN 2G0 604-414-8448 administrator@savaryshoreswater.ca savaryshoreswater.ca

.....Operator to provide estimate.

4c. Meter replacement schedule

The operator had recently replaced Lot-A's meter, and would be replacing meters at lots-143 and -142 on December 17. The trustees agreed that replacing 2 meters per year would be adequate, as testing had shown the used 25-year-old meters to be still accurate. Chair Gregory suggested that we continue to have the extracted meters tested for accuracy, and should they start to show deterioration, SSID could revise the meter replacement schedule accordingly.Operator to continue having old meters tested.

5. Administrator's Report J.Reimer

5a. CWSA conference

5b. Schedule of important 2021 dates

The administrator noted that since SSID is now allowed to conduct its AGM in the summer, the trustees might decide Sunday July 4 or Sunday August 1. After discussion, it was decided that the date would be discussed again in the new year, and a decision made no later than March or April.

.....Administrator to add to next agenda.

5c. Taxes for 2020 all paid.

5d. Bank and reserve funds

The administrator said that the current reserves would be reduced further this year after invoices from Newport Electric were received and paid, and that there would also be a \$17,000 increase to reserves at year end when the 2020 operating surplus was transferred into the reserves account. She also noted that there were no worthwhile term accounts into which SSID might invest the funds from the 2020 asset renewal levy.

5e. Asset Management Plan

Trustee Miles raised the question of whether or not SSID needs an enclosure around well-2. He said that the padlock was already quite secure. A chain-link fence might be more secure, but could be climbed. Trustee Revitt thought it a good idea to secure the wellhead further, for due diligence, especially with a campground being immediately adjacent. The trustees considered that it might not be necessary to access the well until such time that it needs servicing or replacement, so until then 4 chain-link walls

with 1 being removeable, might be adequate. The administrator said she would ask the contractor to revisit his quote, and include this no-access option......Administrator to get updated estimate.

5f. Budget 2021 draft

The administrator reviewed the expected revenues and expenses to come in 2021. The revenues reflected a zero increase in tax rates, as proposed by Trustees Revitt and Miles in consideration of possible financial challenges facing SSID lot owners during this COVID period. Chair Gregory agreed.

There were no notable differences between the expenses of 2021 and 2020. Trustee Miles explained that the \$12,000 amortization expense was added back into the surplus figures, and from that surplus SSID is able to augment its reserves.

5g. 2021 Taxes Bylaw draft

The trustees read and approved the 2021 Tax Bylaw.

.....Chair Gregory to output 2 copies, sign, and mail to the administrator.

5h. 2020 Excess Tolls

Motion			
THAT the Excess Toll for 2020 remain at \$1 per cubic metre over the allotted 100 cubic metres per			
residence	Moved J.Revitt, 2nd B.Miles. Carried.		

5i. Updated customer list provided.

Adjourned 11:30 AM.